

					7.5		7.26	48.76
11.42.03.39	Tower repair rear wheel arch inner Mk1-5	M Machine	04/05/2005	10				
11.14.00.57	Wheel arch corner LH			3.75				
11.14.00.58	Wheel arch corner RH			3.75				
11.14.10.07	Arch to door repair			6.75				
11.14.10.08	Arch to door repair			6.75				
11.41.00.18	Rear seat corner repair RH	M Machine	14.04/2005	0	8		6.83	45.83
11.14.05.04	Seam cover rear RH			4.25				
	Argon/Carbon Welding Gas	Arcrite	13/04/2005	8.95			0.74	4.99
	Argon/Carbon Welding Gas	Arcrite	13/04/2005	8.95				
11.41.00.27	Side repair boot floor LH Mk 1-5	M Machine	12/04/2005	17.5			3.13	21.03
11.41.00.28	Side repair boot floor RH Mk 1-5			17.5				
11.41.03.03	Stiffener rear wheel arch to bulkhead LH			8				
11.41.03.04	Stiffener rear wheel arch to bulkhead RH			8				
11.41.04.04	Stiffener Wheel Arch RH Mk1-5			6				
11.41.00.18	Rear seat corner repair RH			6.5				
11.42.03.27	Wheel Arch Outer, LH Mk1-5			16				
11.42.03.28	Wheel Arch, outer, RH Mk1-5			16				
01.52.16.00	Knuckle Joint			6				
2A5818	Rear Subframe Bushes Small			4.4				
		M Machine			9		21.16	142.06
11.34.04.68	Floor rear Quarter RH Mk1-5	M Machine	29/03/2005	13.5	8.5		3.85	25.85
	Black PU Sealer		02/12/2004	7.91				
	Aerosol Etch Primer		02/12/2004	13.86				
	Grey Primer		02/12/2004	5.24				
	Black Gravigard		02/12/2004	7.76				
		A.C. Refinish					5.29	35.53
	Argon/Carbon Welding Gas	CFM	01/12/2004	8.5				
	Dust Mask			1.46				
			01/12/2004				2.26	15.14
	RH Inner sill to first groove.	M Machine	27/10/2004	28				
	RH Jacking Point.			6.5				
	Rear storage pocket lower repair.			8.5				
	Rear storage pocket closing plate.			3.75				
	RH Subframe end repair.			4				
	Pair nipple shrouds.			10				
		M Machine		12.38			12.38	83.13
11.21.00.27	Hinge Bracket, Apex Panel upper LH MK1-2		15/04/2004	4.25				
11.21.00.28	Hinge Bracket, Apex Panel Upper RH MK1-2			4.25				
		M Machine					1.75	11.75
11.21.00.47	Inner wing repair panel upper LH MK 1-2		06/04/2004	6.5				
11.21.00.48	Inner wing repair panel upper RH MK 1-2			6.5				
11.25.01.03	Closing panel windscreen corner RH MK 1-5			4.2				
11.25.01.04	Closing panel windscreen corner LH MK 1-5			4.2				
11.24.04.05	Gasket Master cylinder MK 1-5			0.75				
31G279	Shim master cylinder			0.52				
	5/16 Bolts, Nuts and washers, front panel/subframe			0.5				
		M Machine - Darlington					4.97	33.39
11.16.00.17	Scuttle corner		16/12/2003	6				
11.16.00.18	Scuttle Corner			6				
11.24.04.05	Gasket			0.75				
11.24.05.05	Gasket			0.75				
11.21.00.58	Inner wing RH lower repair			10.5				
		M Machine			6.75		5.38	36.13
	Half Inner Wing and Cowl LH		19/08/2003	58				
	Half Inner Wing RH			35				
	Front panel diagonal stiffener			3.5				
	Pair shock absorber brackets			22				
	Door sets, Upper chrome fixings			8				
	Remote gear lever gaiter			22.5				
		M Machine			7.5		27.38	183.88
14A7240	MK1/2 RH Front Wing		16/08/2003	30.43				
14A7241	MK1/2 LH Front Wing			30.43				
14A8308	Front Panel Genuine MK1/2			55				
		Mini Spares - Hertfordshire					20.28	136.14
13H525	Clip for door moulding		05/08/2003	1.8				
14A7781	Grille surround MK1			45.09				
14A7783	Grille End Moulding MK1 LH			6.1				
14A9871	Bumper with holes as per MK1 S/Steel			33.62				
24A1304	Window catch runner LH			14.5				
24A88	Original door channel MK1/2			9.2				
ADA3583	MK1 Grille whisker clip S/Steel			1.08				

BHM3	Oversill 6inch RH MK1/2			12.23				
BMP128MS	S/Steel trim clip anti rust			2.76				
MS27R	Inner Sill panel RH			3.5				
		Mini Spares Harrogate			6.38		29.96	201.17
	MK1 LH Door	J.M. Illingworth	31/07/2003	159				159
	Subtotal							1912.46