

Invoice

Brackley Automotive

Bill To: Daimler Sovereign Martin

Invoice No: 288

Date: 16/03/2021

Terms: NET 7

Payment in full upon completion of work 23/03/2021

Description	Quantity	Rate	Amount
Remove carburettors and refit after strip and rebuild	1.2	£50.00	£60.00
Diagnose illumination issue with rear light, strip, clean terminals and run new earth	1	£50.00	£50.00
Diagnose illumination issue with front indicator, strip/clean and repair original wiring	0.5	£50.00	£25.00
Remove both fuel pumps and replace with new supplied units	1.2	£50.00	£60.00
Fit supplied sms tracking device	1.2	£50.00	£60.00
Remove wrong speedo cable and replace with correct one with angle speed drive	1.5	£50.00	£75.00
Speedo cable	1	£36.90	£36.90
Speedo drive	1	£85.00	£85.00
Strip clean oil relief valve	1	£50.00	£50.00
Modify spare wheel clamp to accept wider wire wheel	1	£50.00	£50.00
Strip down both front doors to refit wing mirrors and make secure, adjust drivers window/for rubber	1.5	£50.00	£75.00
Replace all flexi fuel lines	1	£50.00	£50.00
Fuel line and clips	1	£12.00	£12.00
Fuel filter	1	£4.50	£4.50
Remove faulty under dash fuse box and replace with a used replacement	1.5	£50.00	£75.00
Used main fuse box and cover	1	£10.00	£10.00
Diagnose fuel gauge reading fault, replace o/s fuel sender unit with new unit	1.5	£50.00	£75.00
Fuel sender	1	£52.50	£52.50

Description	Quantity	Rate	Amount
Diagnose windscreen wiper issue, remove wiper motor and refit rebuilt unit	1.5	£50.00	£75.00
Subtotal			£980.90
Vat 20% (£980.90)			£196.18
Total			£1,177.08
PAID			£0.00
Balance Due			£1,177.08

Payment Details

Brackley Automotive restoration

63932958
20-16-99

Notes

Vat reg number: 317 2162 30

