



Emblem
SPORTSCARS

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel. 01202 722247
Fax. 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari 360 FERRARI Convertible
3.6 Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 33169
Registered 01/09/2004

SERVICE INVOICE

Service No 9796
Invoice No 11121
Date 12/10/2022
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By 11/10/2023

or

MIs

Service Advisor Martin Chatfield

Brief Service Description

Engine oil and filter change. Lights and levels check. Safety function check over. Waiting.

LABOUR WORK CARRIED OUT

Hours Charged	Total	VAT Rate
2.50	231.25	20.00%
	0.00	20.00%
LABOUR TOTAL:		231.25

Carried out engine oil and filter change. Carried out safety function check over and report. Checked lights, levels, tyre pressures and torque wheel bolts.

Carried out final road test and rechecked all levels and retorqued wheels.

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
197654	Oil Filter (348/360/355)	1	36.82	36.82	20.00%
10263460	Copper Washer	1	0.28	0.28	20.00%
10261860	Copper Washer	1	0.32	0.32	20.00%
PARTS TOTAL:				37.42	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
SHELL 5W-40 (BULK)	10	12.75	127.50	20.00%
			OILS / LUBRICANTS TOTAL:	127.50

EXTRAS

Description	Qty	Total	VAT Rate
Environmental Charge	1	6.95	20.00%
consumables	1	10.00	20.00%
EXTRAS TOTAL:			16.95

ADVISORY

Note - Engine oil pressure sender unit faulty. Front and rear brake pads 90% worn. Front and rear brake discs worn and ridged. Clutch pedal heavy in operation. Front tyres dated 2000. Rear tyres dated 2017. Light play in NSR the rod rose joint.

Continued from previous page...

Service No. 9796

For all work and parts required for the above repairs at your retail charge. All repairs are on a cash basis unless prior arrangements for credit have been approved. I have accepted your terms and conditions (attached). Nothing herein is designed to nor will it affect, in any way, your statutory rights.

Details of how to pay via BACS our bank details are as follows:

Account No 87263301
Sort Code 40-51-62

IBAN: GB31HAND40516287263301
C: HANDEGB22

Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY

All goods shall remain the property of the seller until paid for in full.

Sub Total	413.12
MOT: Standard	0.00
Refest	0.00
+ VAT Due	82.62

Invoice Total	495.74
---------------	--------

Total Payments	0.00
----------------	------

Total Due	495.74
-----------	--------

VAT Analysis

VAT @ 20% on 413.12 = 82.62

Company No. 04446508
VAT No. 840 3145 61

Date..... Signature.....

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel: 01202 722247
Fax: 01202 743620

service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari 360 FERRARI Convertible
3.6 Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 31565
Registered 01/09/2004

SERVICE INVOICE

Service No 9505
Invoice No 10746
Date 22/04/2022
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By 17/06/2022 or MIS

Brief Service Description

Carry out Mot test ***waiting*** Booked Hughes 10.15am

EXTRAS

Description	Qty	Total	VAT Rate
Mot test - Pass	1	40.00	0.00%
mot arrangement fee	1	12.38	20.00%
EXTRAS TOTAL:			52.38

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions (attached). Nothing herein is designed to nor will it affect a customers statutory rights.

If you wish to pay via BACS our bank details are as follows:

Account No 87263301
Sort Code 40-51-62
IBAN: GB31HAND40516287263301
BIC: HANGGB22

Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY
All goods shall remain the property of the seller until paid for in full.

Sub Total **52.38**
MOT: Standard **0.00**
Retest **0.00**
+ VAT Due **2.48**

Invoice Total **54.86**

Total Payments **0.00**

Total Due **54.86**

VAT Analysis
VAT @ 0% on 40.00 = 0.00
VAT @ 20% on 12.38 = 2.48

Company No. 04446508

Date..... Signature.....

VAT No. 840 3145 61

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Registered Office: 118 Old Millon Road, New Milton, Hampshire, BH25 6EB

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel: 01202 722247
Fax: 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari 360 FERRARI Convertible
3.6 Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 29931
Registered 01/09/2004

SERVICE INVOICE

Service No 8984
Invoice No 10114
Date 18/06/2021
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By 17/06/2022

or

MIS

Service Advisor Martin Chatfield

Brief Service Description

Annual service. Cambelt change ****CAR NEEDED FOR 21ST****
LABOUR - WORK CARRIED OUT

Hours Charged	Total	VAT Rate
5.00	417.19	20.00%
4.00	288.25	20.00%
1.00	87.50	20.00%
2.00	175.00	20.00%
1.00	87.50	20.00%
1.00	87.50	20.00%
0.00	0.00	20.00%
0.00	0.00	20.00%

LABOUR TOTAL: 1,055.44

PARTS

Part Number	Description	Qty	Price	Discount	Total	VAT Rate
ZFCNONORB	O Ring - Black	2	0.85		1.70	20.00%
12604274	Wavy Washer 6mm	1	0.05		0.05	20.00%
183898	Bush	1	2.20		2.20	20.00%
179242	Stud	1	4.76		4.76	20.00%
ZFCNONJC	Jubilee Clip	1	1.50		1.50	20.00%
ZFCNONCW	Copper Washer	2	0.75		1.50	20.00%
182119	O Ring	1	1.73		1.73	20.00%
90327506	Speed Clip	2	0.35		0.70	20.00%

Continued from previous page...

Service No 8984

Description	Qty	Price	Total	VAT Rate
Bolt M5x20	1	0.70	0.70	20.00%
Clip Plastic	1	0.19	0.19	20.00%
Battery Positive Terminal Cover	1	29.15	29.15	20.00%
Bulb Lucas LLB380 12v 21/5w	1	1.30	1.30	20.00%
Oil Filter (348/360/355)	1	35.40	35.40	20.00%
Copper Washer	1	0.31	0.30	20.00%
Brake Paste	1	1.00	1.00	20.00%
Tutela Extreme HT Brake Fluid 500ml	2	12.00	24.00	20.00%
Tutela Screen Wash 250ml	1	2.50	2.50	20.00%
Pollen Filter (360/430)	1	54.62	52.50	20.00%
Injector Cleaner	1	8.95	8.95	20.00%
Brake Cleaner 500ml	1	5.95	5.95	20.00%
USE				
10263460 Copper Washer	5	0.26	1.30	20.00%
184886 Timing Belt (360/355)	2	101.25	198.52	20.00%
201454 Power Steering Belt (360)	1	11.46	11.24	20.00%
201446 Alternator Water Pump Belt (360)	1	24.29	23.34	20.00%
201236 AC Belt (360)	1	14.77	14.20	20.00%
PARTS TOTAL:			424.68	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
SHELL 5W-40 (BULK)	10	12.00	120.00	20.00%
PARAFLU 11 - ANTIFREEZE (BULK)	5	6.50	32.50	20.00%
SPIRAX S5 ATE 75W90	5	9.00	45.00	20.00%
OILS / LUBRICANTS TOTAL:			197.50	

EXTRAS

Description	Qty	Total	VAT Rate
consumables	1	20.00	20.00%
Environmental Charge	1	6.95	20.00%
EXTRAS TOTAL:		26.95	

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions (attached). Nothing herein is designed to nor will it affect a customer's statutory rights.

If you wish to pay via BACS our bank details are as follows:
 Account No 87263301
 Sort Code 40-51-62
 IBAN: GB31HAND40516287263301
 BIC: HANDGB22
 Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY
 All goods shall remain the property of the seller until paid for in full.

Sub Total	1,704.57
MOT: Standard	0.00
Refest	0.00
+ VAT Due	340.92
Invoice Total	2,045.49
Total Payments	0.00
Total Due	2,045.49

VAT Analysis
 VAT @ 20% on 1,704.57 = 340.92

Date:

Signature:

Company No. 04446508
 VAT No. 840 3145 61

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel: 01202 722247
Fax: 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari 360 FERRARI Convertible
3.6 Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 29350
Registered 01/09/2004

SERVICE INVOICE

Service No 8903
Invoice No 10021
Date 30/04/2021
Payment
Order No

Your Ref HAVILLP

Next Service Due By

or

Mis

Telephone 07836 228065
Email patrickhavill@icloud.com

Brief Service Description

Mot test - 11.45 am Hughes Workshop
EXTRAS

Description	Qty	Total	VAT Rate
Mot test - Pass	1	40.00	0.00%
mot arrangement fee	1	12.38	20.00%
EXTRAS TOTAL:			52.38

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions (attached). Nothing herein is designed to nor will it affect a customers statutory rights.

If you wish to pay via BACS our bank details are as follows:

Account No 87263301

Sort Code 40-51-62

IBAN: GB31HAND40516287263301

BIC: HANDGB22

Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY

All goods shall remain the property of the seller until paid for in full.

Sub Total **52.38**
MOT: Standard **0.00**
Retest **0.00**
+ VAT Due **2.48**

Invoice Total **54.86**
Total Payments **0.00**

Total Due **54.86**

VAT Analysis

VAT @ 0% on 40.00 = 0.00
VAT @ 20% on 12.38 = 2.48

Date:..... Signature.....

Company No. 04446508
VAT No. 840 3145 61

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel. 01202 722247
Fax. 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari 360 FERRARI Convertible
3.6 Petrol
Registration S55P GH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 28529
Registered 01/09/2004

SERVICE INVOICE

Service No 8439.02
Invoice No 9480
Date 01/07/2020
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By

or

MIs

Brief Service Description

Investigate roof operation. RH upper cross member cracked and header rail classic trim adrift. Roof folding correctly?
LABOUR - WORK CARRIED OUT

Hours Charged	Total	VAT Rate
Investigated operation of roof. Found RH upper cross member to be cracked, rear screen folding incorrectly, centre main roof beam not folding back correctly, hydraulic fluid level low and light oil leak from LHR main compartment ram.	0.00	20.00%
Replaced RH upper roof cross member with new new bolts as required	0.00	20.00%
Fitted return spring to roof centre cross bar to ensure roof folds the correct way.	0.00	20.00%
Cleaned rear window. Topped up roof hydraulic fluid. Checked roof operation stage by stage. Lubricated all roof pivot points. Checked lights, levels, tyre pressures and torqued wheel bolts. Carried out road test, ok.	0.00	20.00%
Labour	4.00	350.00 20.00%
LABOUR TOTAL:		350.00

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
81096100	RH Front Top Crossmember	1	633.56	633.56	20.00%
PARTS TOTAL:				633.56	

EXTRAS

Description	Qty	Total	VAT Rate
consumables	1	10.00	20.00%
EXTRAS TOTAL:		10.00	

Continued from previous page...

Service No 8439.02

for all work and parts required for the above repairs at your retail charge. All repairs taken on a cash basis unless prior arrangements for credit have been approved. I have accepted your terms and conditions (attached). Nothing herein is designed to nor will it affect, owners statutory rights.

I wish to pay via BACS our bank details are as follows:

Account No 87263301

Sort Code 40-51-62

IBAN: GB31HAND40516287263301

BIC: HANDGB22

Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY

All goods shall remain the property of the seller until paid for in full.

Sub Total	993.56
MOT: Standard	0.00
Retest	0.00
+ VAT Due	198.71

Invoice Total	1,192.27
---------------	----------

Total Payments	0.00
----------------	------

Total Due	1,192.27
-----------	----------

VAT Analysis

VAT @ 20% on 993.56 = 198.71

Company No. 04446508

VAT No. 840 3145 61

Date..... Signature.....

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel: 01202 722247
Fax: 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model 360 FERRARI 3.6 2dr Convertible
Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 26074
Registered 01/09/2004

SERVICE INVOICE

Service No 7559
Invoice No 8412
Date 27/11/2018
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By

or

MIs

Service Advisor

Martin Chatfield

Brief Service Description

Continued work from last month

LABOUR WORK CARRIED OUT

Hours Charged	Total	VAT
Investigated 'Check Engine' light issue.	0.00	20.00%
Pressure tested cooling when engine cold, removed coils and spark plugs, used bore scope camera to check for coolant leaking into cylinders / possible head gasket. Left pressure tester on for 4 hours, no signs of coolant leak into cylinders.	0.00	20.00%
Carried out engine compression test, all ok at 12 - 13 bar.	0.00	20.00%
Checked fuel pressure and delivery rate from both fuel pumps, ok. Checked fuel rails holding pressure after switching engine off, ok.	0.00	20.00%
Checked fuel injectors and found some leaking when hot (spray pattern not consistent). Supplied and fitted new fuel injectors using new seals.	0.00	20.00%
Removed pre cat lambda sensors, used bore scope to check cat condition, ok. Fitted new lambda sensors.	0.00	20.00%
Connected Ferrari tester to engine ECU's and reset throttles and self learnt parameters. Carried out several road tests / cold start tests, ok. Customer to drive and test.	0.00	20.00%
Labour	5.00	437.50 20.00%
LABOUR TOTAL:		437.50

PARTS

Part Number	Description	Qty	Price	Total	VAT
197808	Fuel Injector	8	176.03	1,408.24	20.00%
BSH0258007001	Lambda Sensor	2	74.08	148.16	20.00%
133902	O Ring Seal Injectors	16	4.03	64.48	20.00%
PARTS TOTAL:				1,620.88	

EXTRAS

Description	Qty	Total	VAT
unleaded fuel	1	33.34	20.00%
EXTRAS TOTAL:		33.34	

pay for all work and parts required for the above repairs at your retail charge. All repairs taken on a cash basis unless prior arrangements for credit have been approved. I have accepted your terms and conditions (attached). Nothing herein is designed to nor will it affect, in any way, the rights of the consumer under the Consumer Credit Act 1974 or any other consumer statutory rights.

I wish to pay via BACS our bank details are as follows;

Account No 87263301

Sort Code 40-51-62

IBAN: GB31HAND40516287263301

BIC: HANDGB22

Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY

All goods shall remain the property of the seller until paid for in full.

Sub Total	2,091.72
MOT: Standard	0.00
Retest	0.00
+ VAT Due	418.35

Invoice Total	2,510.07
---------------	----------

Total Payments	0.00
----------------	------

Total Due	2,510.07
-----------	----------

VAT Analysis	
--------------	--

VAT @ 20% on 2,091.72 =	418.35
-------------------------	--------

Company No. 04446508
VAT No. 840 3145 61

Date:..... Signature:.....

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel. 01202 722247
Fax. 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari FERRARI Convertible 3.6 Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 25951
Registered 01/09/2004

SERVICE INVOICE

Service No 7500
Invoice No 8321
Date 16/10/2018
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By

or

Mis

Service Advisor Martin Chatfield

Brief Service Description

Investigate 'Check Engine' light on. Missfire / running rough ref Trim.

LABOUR WORK CARRIED OUT

Hours Charged	Total	VAT Rate
Investigated 'Check Engine' light coming on intermittently. Connected Ferrari SD2 tester to engine ECU's and found errors stored in 5-8 bank (LH side). Errors logged with Emission's out of range and multiple misfire cylinders 2-4	0.00	20.00%
Removed ignition coils fitted in Wales and refitted originals. Checked operation of lambda sensors, all working ok. Found 5-8 bank lambda sensor looks to be running lean and cat temp 80 degrees C hotter than RH bank, suspect air leak.	0.00	20.00%
Removed all engine bay trims to check vacuum pipe work, checked for air leak. Found RH exhaust valve vacuum system not blocked off causing air leak and LH side not blocked off very well. Blocked both vacuum pipes off correctly.	0.00	20.00%
Checked for fuel smell, checked fuel vapor / purge system. Pressure tested system and found leak on carbon canister vent valve. Fitted new vent valve and carbon canister.	0.00	20.00%
Refitted all engine bay trims. Connected Ferrari tester, cleared errors and reset engine self learnt parameters. Ran engine and checked, ok.	0.00	20.00%
Carried out a number of road tests, engine running better, rechecked engine management for errors, all clear.	0.00	20.00%
Checked lights, levels, tyre pressures and torqued wheels.	8.90	778.75 20.00%
Labour	0.00	20.00%
LABOUR TOTAL:		778.75

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
180132	Fuel Filter	1	307.00	307.00	20.00%
179138	On-Off Valve	1	75.53	75.53	20.00%
192637F	Spark Plug NGK PMR8B	4	22.22	88.88	20.00%
PARTS TOTAL:				471.41	

EXTRAS

Description	Qty	Total	VAT Rate
consumables	1	5.00	20.00%
EXTRAS TOTAL:		5.00	

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions (attached). Nothing herein is designed to nor will it affect a customer's statutory rights.
If you wish to pay via BACS our bank details are as follows:
Account No 87263301
Sort Code 40-51-62
IBAN: GB31HAND40516287263301
BIC: HANDGB22
Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY
All goods shall remain the property of the seller until paid for in full.

Sub Total	1,255.16
MOT: Standard	0.00
Retest	0.00
+ VAT Due	251.04

Invoice Total	1,506.20
Total Payments	0.00
Total Due	1,506.20

VAT Analysis	
VAT @ 20% on 1,255.16 =	251.04

Date.....

Signature.....

Company No. 04446508

VAT No. 840 3145 61

Emblem SPORTSCARS

FERRARI LAMBORGHINI MASERATI SPECIALISTS

Emblem Sports Cars Ltd
Unit 2c & 2d Sharp Road
Poole, Dorset BH12 4BG

Tel. 01202 722247
Fax. 01202 743620
service@emblemsportscars.co.uk
www.emblemsportscars.co.uk

Registered Office: 118 Old Milton Road, New Milton, Hampshire, BH25 6EB

INVOICE TO

Mr Patrick Havill+
West Acre
Witchampton
Wimborne
Dorset
BH21 5BX

SERVICED VEHICLE

Make Ferrari
Model Ferrari FERRARI Convertible 3.6 Petrol
Registration S55PGH
Chassis No ZFFYT53C000138825
Engine No 86388
Mileage 23589
Registered 01/09/2004

SERVICE INVOICE

Service No 6716
Invoice No 7381
Date 11/08/2017
Payment
Order No

Your Ref HAVILLP

Telephone 07836 228065
Email patrickhavill@icloud.com

Next Service Due By

or

MIS

Service Advisor Martin Chatfield

Brief Service Description

Investigate throttle working at 25%

LABOUR WORK CARRIED OUT

Hours Charged	Total	VAT Rate
Investigated poor / half throttle operation. Connected Ferrari SD2 to engine ECU's, fault present with throttle pedal potentiometer. Checked connections to potentiometer and make sure good contacts made. Cleared error and reset parameters.	0.00	20.00%
Carried out road test, fault still present / reoccurs. Connected Ferrari tester, throttle pot error present again.	0.00	20.00%
Fitted new throttle pedal potentiometer, cleared errors and carried out road test. Fault still present. Connected Ferrari tester and error logged in RH bank ECU with potentiometer.	0.00	20.00%
Removed engine bay trims, disconnected battery and swapped ECU's bank to bank. Carried out road test, fault still present. Swapped engine ECU's back. Removed carpet trims from both sides of centre console. Found multipugs out of clips / floating around.	0.00	20.00%
Found front underlay damp with antifreeze. Pressurized cooling system and found coolant leaking from front bulkhead rubber grommet and onto main electrical plug for throttle wiring. Checked multiplug and found to be in poor condition.	0.00	20.00%
Removed front luggage compartment trims to gain access to coolant pipes. Found main heater hose clip loose and in poor condition. Drained cooling system, removed pipes and cleaned up connections. Refitted rubber hoses with new hose clips.	0.00	20.00%
Refilled cooling system and pressure tested, ok. Removed and dried out carpets / underlay. Removed battery and battery tray as not fitted correctly. Cut off contaminated electrical multiplug and fitted new.	0.00	20.00%
Also found 3 other wires on loom in poor condition where an electrical device has been fitted and removed. Repaired wires as required. Ran engine and checked all ok, no errors, engine and throttle working correctly.	0.00	20.00%
Refitted battery tray and battery correctly, fitted breather pipe. Refitted carpets. Cleared and reset engine management. Reset both throttles.	0.00	20.00%
Investigate operation of O/S door lock - reconnected inner door handle clip.	0.00	20.00%
Carried out road test and checked for errors, all clear. Checked lights, levels, tyre pressures and torqued wheels. Topped up PAS fluid.	0.00	20.00%
Labour	12.36	20.00%
	1,050.60	20.00%

LABOUR TOTAL: 1,050.60

Number	Description	Qty	Price	Total	VAT Rate
CONJIC	Jubilee Clip	2	1.25	2.50	20.00%
FCONMIP	Multiplug	2	3.95	7.90	20.00%
PARTS TOTAL:				10.40	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
PARAFLU 11 - ANTIFREEZE (BULK)	5	6.75	33.75	20.00%
OILS / LUBRICANTS TOTAL:				33.75

EXTRAS

Description	Qty	Total	VAT Rate
Covered transportation - Home address to Emblem	1	60.00	20.00%
Consumables	1	10.00	20.00%
EXTRAS TOTAL:			70.00

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions (attached). Nothing herein is designed to nor will it affect a customers statutory rights.

If you wish to pay via BACS our bank details are as follows:
 Account No 87263301
 Sort Code 40-51-62
 IBAN: GB31HAND40516287263301
 BIC: HANDGB22

Address: Svenska Handelsbanken, 3 Thomas More Square, London E1W 1WY
 All goods shall remain the property of the seller until paid for in full.

Sub Total 1,164.75
MOT: Standard 0.00
Retest 0.00
+ VAT Due 232.95

Invoice Total 1,397.70
Total Payments 0.00

Total Due 1,397.70

VAT Analysis
 VAT @ 20% on 1,164.75 = 232.95

Date..... Signature.....

Company No. 04446508
 VAT No. 840 3145 61