Andrew Galt – Citroen Repair and Restoration



INVOICE

13th May 2021

.... · LLLIalmas

	Make	Model	Registration	Mileage
SALES CONTRACTOR	Citroen	11 BL Legere	OSL 282	

Qty	Description	8.	Total £
	Investigate oil leak and clutch slip. Remove engine and gearbox, separate and remove clutch assembly. Supply and fit replacement friction plate and release bearing. Degrease and clean all components and bellhousing. Re-set clutch and re-assemble. Remove top of gearbox, reseal and refit. Supply and fit bellhousing cover plate. Remove non-standard breather and supply and fit standard item. Refit engine and gearbox to the car and reassemble all ancillaries. Test run.		
	Clean and set plugs and points. Make adjustments to the timing and carburettor. Change engine oil (supplied) and top up gearbox oil. Grease/lubricate engine compartment as needed.		
	Raise car and check steering and front suspension. Separate rhs track rod end and lower ball joint. Fit replacement ball joint gaiter and re-assemble and adjust. Grease steering, suspension and driveshafts.		
	Remove all wheels and brake drums and check brake condition. Very slight contamination of front rhs leading shoe (grease from drilled hub) Clean drums etc and re-assemble. Adjust all brake shoes. Adjust and balance parking brake. Check and adjust all tyre pressures as needed.		
	Make adjustments to the driver's seat position.		
	Tighten both front mud flaps to the body and front number plate to bumper.		
	Dress out dents in hubcap centres.		
	Test drive.		
	Labour : 26.5 hours @ £35.00		927.50
	Parts: Clutch friction plate £60.00 Release bearing £20.00 Top hose £18.00 Ball joint gaiter £7.50 Gearbox oil/grease £2.50 Bell housing cover and crank case breather £25.00		133.00