

OSL 282 – Maintenance & Service Record

Engine Oil: Duckhams Classic SAE40 - Last Change: 11th June 2020 @ 33,838 Km

Gearbox Oil: Castrol ST90 Mineral (GL-3) last change 11th June 2020 @ 33,838 Km

Coolant: Prestone Extreme: 11th June 2020 @ 33,838 Km

Water Pump: Replaced Feb 2014 @ 15,949 Km

Fan Belt: Gates B38 MN Replaced 14th August 2018 @ 31,010 Km

Fuel Pump + Filter: 100% Ethanol safe + hose, Copper pipe – 7th April 2020 @ 33,740 Km

Fuel Tank Sender: Replaced 4th July 2018 @ 30,460 Km

Fuel Tank: replaced 11th March 2016 @ 24,040 kms

Carburettor: Solex Copy, February 2018 @ 29,980 Km – rebuilt December 2018 @ 31,425 Km

Spark Plugs: EYQUEM N 43 F3+1 last change 4th July 2018 @ 30,640 Km

Suspension: Quicksilver 2-4-C Marine Grease – All nipples done 3rd March 2020 @ 33,720 Km

Air Filter: K&N E-3506 High Flow Washable Fitted: 7th April 2020 @ 33,740 Km

Coil: NOS 12v Marchal Coil fitted 2nd November 2016 @ 27,125 Km + new HT leads

Alternator: 12v Fitted 25th October 2013 @ 15,670 Km

Battery: 12v Excel 65 Amp Hour Fitted 6th December 2017 @ 29,900 Km

Bulbs: (12v) + Fuses all replaced/fitted October 2016 @ 26,980 Km

Brakes: All Relined + all new cylinder & master cylinder seals - April 2013 @ 13,145 Km

Brake Fluid: Duckhams Dot 4 – last change: 11th June 2020 @ 33,833 Km

Tyres: Original Michelin X – 4 New + Tubes + Tracking April 2013 @ 13,145 Km

Shock Absorbers: Front and Rear replaced 26th July 2019 @ 33,216 Km

Exhaust: LongLife Custom Stainless fitted 6th June 2013 – Lifetime Warranty

February 2014

Engine & Gearbox – Oil Leak investigated

While engine was out:

Sump cleaned and fitted new magnetic drain plug

Clutch checked – was relined 2012 before car bought and OK as was pressure plate

June 2017

Remote Brake Servo unit fitted, brake fluid changed.

September 2017

Both front seat base spring sets replaced

October 2017

Axle Weight Distributions checked and car weight balanced via racing scales, adjusted and all within Citroen tolerance.

February 2018

Replacement Copy Solex Carburettor fitted.

August 2018

Gearbox removed/rebuilt with new 9:31 Crown Wheel and Pinion, replacement 1st gear, new bearings, gaskets etc.

Clutch inspected, cleaned and adjusted, plus new release bearing fitted whilst gearbox removed.

Camshaft pulley replaced, 2 new bearings fitted to extension shaft + new Odhams coupling

Gearbox Oil, Engine Oil and Fan Belt replaced + top radiator hose.

Brakes Adjusted and full safety inspection carried out.

October 2018

Revised crankcase breather made and fitted.

November 2018

Radiator Fan blade replaced, new engine block coolant plug fitted, new lower hose + coolant renewed.

December 2018

Carburettor rebuilt.

January 2019

123 Electronic distributor removed and replaced with a new Ducellier Type Mechanical distributor.

February 2019

Cylinder head removed, valve seats re cut then rebuilt with all new valves, valve guides, seals, inner and outer springs, rocker shaft and rockers. Water tube and core plugs replaced, manifold refaced, new head and manifold gaskets etc.

Rear LED light units fitted.

July/August 2019

Shock Absorbers Replaced. Reconditioned Oil Pump fitted with new sump gaskets.