

Photographic Record of the Restoration of

1970 MGB Roadster ATG 932J.

Undertaken By Millard Auto Services, Thornbury, Bristol.

2019/2020



































































































UNDERTAKEN & PARTS USED (Not Exhaustive).

ation Supplied Where Appropriate By The Previous Owner.

```
iring Loom.
nition Leads.
```

ater Radiator and associated pipework.

Radiator and associated pipework.

ar and Front Springs.

pers Rebuilt.

el Tank.

el Lines.

pper Brake Lines & Associated Brackets

ake Discs & Callipers.

aster Cylinder.

utch. el Pump.

nic Ignition.

rpets.

fety Belts.

mpers.

sh Steering Rack, new gaiters and track rod ends.

are Metal Body Strip (All panels and all surfaces).

te Respray of all surfaces

eadlamps and partial LED bulbs.

te Engine Strip Down and Rebuild.

ainless Steel Exhaust. at Squabs.

and Repainted Heater Box.

w Tyres.

heels Repainted.

oke Cable. ot & Bonnet Insulation Panels.

rd Top Rear Window.

rd Top Rear Window.

or Cards and Internal Chrome Door Pulls. (Not Main).

ather Gear Stick Gaiter.

ervice/Refurb.

itch Master and Slave Cylinders.

licator Switch.

dicator Lamps//Front.

eering Col Cowl.

erdrive Solenoid and Dash Switch

le Check Straps.
ndbrake Cable.
asher Jets.
le Trim Chrome.
ndow, Bonnet and Door Seals.
nk fittings hose and filler cap.
Cut Off Switch fitted.